

Dosage Charts

Lowering Total Alkalinity in Spas

Muriatic Acid for SPAS

All amounts are in Fluid Ounces

	Gallons in Spa			
PPM	2,000	1,500	750	400
10	5.2	3.9	1.9	1
20	10.4	7.8	3.9	2
30	15.6	11.7	5.8	3.1
40	20.8 ($\approx 1 \frac{1}{3}$ pint)	15.6	7.8	4.2
50	26 ($\approx 1 \frac{2}{3}$ pint)	19.9 ($\approx 1 \frac{1}{4}$ pint)	9.7	5.2

Dry Acid for SPAS

All amounts are in Ounces

	Gallons in Spa			
PPM	2,000	1,500	750	400
10	6.8	5.1	2.5	1.4
20	13.6	10.2	5.1	2.7
30	20.4 (≈ 1.28 lbs)	15.3	7.6	4
40	27.2 (≈ 1.69 lbs)	20.4 (≈ 1.28 lbs)	10.2	5.4
50	34 (≈ 2.13 lbs)	25.5 (≈ 1.6 lbs)	12.7	6.8